

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5727	DATE	October 28, 2025
MANUFACTURER	Trantechs, Ltd.		
DESCRIPTION OF DEFECT	In some hanging-type fire extinguisher brackets, cracks may develop due to insufficient design review and vibration while driving. If the vehicle continues to be used in this condition, the cracks could grow, and in the worst case, the fire extinguisher box may fall off and obstruct other traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-XZU710M 2RG-XZU710M 2PG-XZU710M	Dutro	2019～2023	4
2KG-XZU712M		2023～2024	3
2KG-XZU775M		2020～2022	2
2SG-XKU712M 2QG-XKU712M		2021～2024	2
2PG-FD2ABG 2KG-FD2ABG	Renger	2019～2024	2
2KG-FE2ACA		2024	1
2PG-FW1EHG	Profia	2019	1
2RG-NPR88YN	Elf	2022	2
2RG-FRR90T2	Forward	2023	2
2RG-FTR90V4		2024	1
		TOTAL	20