

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	5744	DATE	2. Dec. 2025
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Regarding the repair parts of the speed transmission gear unit, due to unsuitable material of the internal part of the subject unit, there are cases where the hardness of the part is insufficient. Because of this, the speed transmission gear unit may deform when the axle shaft is tightened, and as the result, the rotation of the tire is not transmitted, the speedometer becomes inoperative, and the products may not conform to the safety standards for road vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
4JG	YAMAHA SEROW XT225W	1996	1
TOTAL			1

Something shipped as a repair part and for which the assembled vehicle cannot be identified.

PART NAME	PART NUMBER	MODEL YEAR PART	NUMBER OF PART
SPEED TRANSMISSION GEAR UNIT	4TR-25190-20	2025	87
	4HM-25190-20	2025	31
	34X-25190-01	2025	10
	1FK-25190-02	2025	6
	5EK-25190-00	2025	4
	4KG-25190-20	2025	3
TOTAL			141

Vehicles with repair parts assembled shall be subject to the same improvement.