

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5750	DATE	December 10. 2025
MANUFACTURER	Kawasaki Motors, Ltd.		
DESCRIPTION OF DEFECT	The bolts holding the crankshaft together in the crank case were tightened with excessive axial force, and as a result the metal crankshaft bushing can be damaged by improper oil clearance between the crankshaft and the bushing. This may cause engine stall during operation,		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
8BL-ZX636J	「Ninja ZX-6R」	2024, 2025	1,930	
		TOTAL	1,930	