

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	5751	DATE	December 15.2025
MANUFACTURE	Topre Corporation		
DESCRIPTION OF DEFECT	<p>In the power supply wiring for the refrigeration unit of battery electric vehicles, insufficient design consideration resulted in the wiring being secured in a bent condition, which may apply stress to the wiring connector and create a gap in the internal waterproof packing. Consequently, water may enter the connector and cause an electrical leakage in the power supply wiring. When this occurs, a warning is displayed and the vehicle's protection function is activated; if the vehicle comes to a complete stop, it cannot be restarted, leading to an inability to drive.</p>		