

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN  
JAPAN

Domestic Vehicles

CAMPAIGN No.	5752	DATE	Dec 15, 2024
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to an inappropriate tightening instruction, the screws securing the rear brake master cylinder reservoir tank cap may have insufficient tightening torque. Continued use of such screws without correction could lead to its loosening and subsequent brake fluid leakage. In the worst case, the brake fluid in the reservoir tank could deplete, potentially extending the braking distance.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-ER1AH	DR-Z4SM	2025	620
8BL-ER1AH	DR-Z4S	2025	365
		TOTAL	985