

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	5749	DATE	December 16 ,2025
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	<p>Regarding the joint that connects the power steering pump and the oil hose, due to an improper assembly method for the joint, the O-ring may be damaged during assembly. As a result, if the vehicle continues to be operated in this condition without repair, power steering oil may leak from the joint, and in the worst case, steering effort may increase.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FVR26U4 2PG-FVR26U4	[FORWARD]	2024-2025	44
2DG-FVZ26U4		2024-2025	258
2KG-BVR26U4 2PG-BVR26U4	[CONDOR]	2024-2025	10
2DG-BVZ26U4		2024-2025	37
		TOTAL	349