

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5748	DATE	December. 18. 2025
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>When the engine is rotating at a high speed, repeatedly slowing down by using engine braking may cause the engine oil to be drawn up to the combustion chamber and combusted, increasing the oil consumption. Because of this, if the vehicle continues to be used in this condition, the engine may start making abnormal sounds due to poor oil lubrication, and in the worst case, the engine may be damaged while the vehicle is running, which has a risk that the rear wheel may lock, causing the vehicle to overturn.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-PC40	「CBR600RR」	2024～2025	2,389
8BL-SC94	「CB1000F」 「CB1000F SE」	2025	1,341
8BL-SC86	「CB1000 HORNET」 「CB1000 HORNET SP」	2024～2025	620
TOTAL			4,350