

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5753	DATE	December 24, 2025
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	<p>Regarding the harvest lifting cylinder of combine, it can cause oil to leak from the connection between the cylinder and the joint because of improper processing in the cylinder components. When leaking oil from cylinder, the hydraulic pressure required to raise and lower the harvest unit is insufficient, causing symptoms such as the harvesting unit becoming difficult to raise or even descending on its own. Furthermore, if the oil leak is not noticed and the vehicle is continued to be used, there is a risk that the amount of oil required to run the machine will be insufficient, causing it to become unable to run.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
—	ER448N	18/4/2025～23/9/2025	926
—	XC448	1/5/2025～8/8/2025	33
C328	R325	21/4/2025～24/9/2025	187
—	XC325	1/5/2025～7/8/2025	12
YDM-C441	KR448	18/4/2025～23/9/2025	104
YDM-C442	KR438	18/4/2025～16/7/2025	8
YDM-C331	KR338	21/4/2025～24/9/2025	56
—	XC334	4/6/2025～2/7/2025	5
C330	KR323	8/7/2025～26/9/2025	204
—	XC323	4/8/2025	4
—	XC321	4/8/2025	1
C236	KR220	8/7/2025～26/9/2025	116
—	XC220	1/9/2025	1
	TOTAL		1657