

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	5754	DATE	December 24, 2025
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	<p>In the power transmission device (HST assembly) of combine, the hardness of the internal components (cylinder block) may be below the standard value due to an improper manufacturing process. When this happens, the components may be damaged by the load when the machine is running, and the power required for running may not be obtained, which may result in the vehicle becoming unable to run.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-C524	DR575	14/4/2025～19/9/2025	93
–	DR595	11/4/2025～23/9/2025	86
–	DR6130	11/4/2025～25/9/2025	322
YDR-C701	DR7130	14/4/2025～3/9/2025	34
		TOTAL	535