

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5758	DATE	January 7, 2026
MANUFACTURER	Mitsubishi Logisnext Co., Ltd		
DESCRIPTION OF DEFECT	<p>In forklift trucks, exhaust gas recirculation (EGR) system components, including the EGR valve and EGR pipe, as well as the pipe brackets, harness stay, and cooler stay, may have been installed with incorrect bolt-tightening-tool selection. Therefore, some mounting bolts may not have been tightened to the specified torque, and the bolts may loosen, potentially causing exhaust gas leakage. In addition, ingestion of foreign objects or detachment of parts could lead to engine damage and, in the worst case, render the vehicle inoperative.</p> <p>(Violation of the Safety Regulations for Road Vehicles in Japan.)</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
YDM-F14F	「ERSIS」	2025	1
YDM-F18D			35
		TOTAL	36