

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	5767	DATE	January 22 ,2026
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		Due to improper work instructions in the manufacturing process, some drag links had the label indicating the front side affixed to the rear side. As a result, drag links were installed in vehicles with the front and rear reversed, which reduces the clearance between drag links and tires. Consequently, when tire chains are installed, drag links may come into contact with tire chains.	

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
2PG-FRS90J4□ 2RG-FRS90J4	[FORWARD]	2025	56
2PG-FSS90J4□ 2RG-FSS90J4		2025	11
2PG-BRS90J4□ 2RG-BRS90J4	[CONDOR]	2025	4
2PG-BSS90J4□ 2RG-BSS90J4		2025	7
		TOTAL	78

Vehicles Which Had The Affected Parts Installed After They Rolled Off The Assembly Line

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
KK-FRS33H4J	[FORWARD]	2025	1
TKG-FRS90S2		2025	2
PDG-FSS90S1□ 2RG-FSS90S2		2025	2
		TOTAL	5

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF □ VEHICLE
Drag Link	1-44380202-0 8-97618258-0	2025	7
		TOTAL	7