

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5755	DATE	January-23-2026	
MANUFACTURER	PABCO CO.,LTD			
DESCRIPTION OF DEFECT	Due to insufficient design review of the side guard (anti-entanglement device), some vehicles have the reinforced section of the side-guard stay positioned too close to the fuel tank band that secures the fuel tank. As a result, vehicle body movement during driving may cause interference between the reinforced section of the side-guard stay and the fuel tank band. In the worst case, the fuel tank band could be damaged, causing the fuel tank to detach and potentially obstruct other traffic.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
2PG-FS74HZ	FUSO SUPER GREAT	2024		2
2PG-FS75HZ		2024		1
2PG-FS84GZ		2024	~ 2025	3
2PG-FS84HY		2025		4
2PG-FS84HZ		2024	~ 2025	58
2PG-FS84VZ		2024	~ 2025	207
2PG-FS85HZ		2024		2
2PG-FS85VZ		2024	~ 2025	34
			TOTAL	