

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5770	DATE	January.28.2026
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>Due to an inadequate circuit design of the rear door opener switch in the rear door handle, if water is accumulated near the switch and the door is closed forcefully, there is a possibility that the seal performance temporarily may be reduced and water enters into the switch, causing a short circuit. Therefore, the rear door may become half-open and the warning light will illuminate. In the worst case, the rear door may open unexpectedly.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
6AA-MXWH60	[PRIUS]	2022-2025	140,314	
6LA-MXWH61			24,119	
6AA-MXWH65			26,370	
6AA-ZVW60			41,796	
6AA-ZVW65			6,905	
		TOTAL	239,504	