

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| | | | |
|-----------------------|--|---------|-------------|
| CAMPAIGN No. | 5771 | D A T E | Feb.5. 2026 |
| MANUFACTURER | SUBARU CORPORATION | | |
| DESCRIPTION OF DEFECT | In the electric power steering system, there are some vehicles in which the harness connector was not properly mated due to incorrect installation. As a result, if the connector becomes disconnected due to driving vibration or the like, the warning lamp may illuminate, and the steering operating force may increase. | | |

| T Y P E | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|---------|-----------------|---------------------|-------------------|
| 4BA-VN5 | 「LEVORG」 | 2025 | 648 |
| 5BA-VNH | | | 12 |
| 5BA-VBH | 「WRX」 | | 96 |
| | | TOTAL | 756 |

Vehicles that may have been assembled with the parts shipped as replacement repair parts

| T Y P E | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|---------|-----------------|---------------------|-------------------|
| 4BA-VN5 | 「LEVORG」 | 2021 | 1 |
| | | 2025 | 1 |
| | | TOTAL | 2 |

Parts shipped as repair parts that could have been assembled but the vehicle cannot be identified.

| PARTS | PARTS NUMBER | SHIPMENT PERIOD | NUMBER OF PARTS |
|---------------------|--------------|-----------------|-----------------|
| 「STEERING GEAR BOX」 | 34110VC113 | 2025 | 1 |
| | | TOTAL | 1 |