

第4号様式(英文リコール概要書) (第2関係)

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5757	DATE	2026/2/9
MANUFACTURER	YANMAR CONSTRUCTION EQUIPMENT CO., LTD.		
DESCRIPTION OF DEFECT	<p>In the cab lamp of the shovel loader, improper work instructions have caused some installation clips to break during mounting. Consequently, vehicle vibration may cause the cab lamp to detach. If the lamp's metal parts then contact the cab body, causing an electrical short circuit, the fuse may blow. This could result in the monitor failing to illuminate. In the worst case, the turn signals may cease to function.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDM-V37	「V3-7」	2022 to 2025	316
V37E	「V3-7S」	2022 to 2025	472
YDM-V47	「V4-7」	2022 to 2025	568
YDM-V57	「V5-7」	2022 to 2025	82
YDM-RW06	「LK40Z-6」	2022 to 2024	44
RV06	「LK40ZST-6」	2022 to 2024	64
YDM-RX06	「LK50Z-6」	2022 to 2025	167
TOTAL			1,713

(日本工業規格A列4番)