

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5774	DATE	February 18, 2026
MANUFACTURER	Trantechs, Ltd.		
DESCRIPTION OF DEFECT	Some " Wing power unit" mounting brackets have insufficient strength due to inadequate welding control. Continued use in this condition should cause cracks to form in the welded areas due to vehicle vibration during operation. These cracks should progress and lead to fracture. In the worst case, the " Wing power unit" should detach and obstruct other traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
QPG-FW1EZEG QPG-FW1EZEJ	「Hino Profia」	2014~2017	331	
QPG-FW1EXEG QPG-FW1EXEJ QKG-FW1EXEG QKG-FW1EXEJ		2014~2017	176	
QPG-FW1EBEG		2014	2	
QPG-FW1EYEG		2015~2017	2	
QPG-FW1ABEG		2015~2016	2	
QPG-FW1AXEG		2017	1	
2DG-FW1AHG		2017	4	
QKG-CYJ77A		「Giga」	2015	2
QKG-FS54VZ QPG-FS64VZ		「Fuso Super Great」	2014	3
			2015~2016	2
QKG-CG5ZA	「Quon」	2015	1	
		TOTAL	526	