

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5783	DATE	Feb.25.2026
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	During repeated engine starts and in start-stop operation, the contacts experience abnormal wear, and wear particles may accumulate beneath the lower contact point. Over the service life of the starter, this impairs the engine's starting capability. Under certain circumstances, it may no longer be possible to start the engine. In the worst-case scenario, there is a risk of fire either when activating the starter or while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
3BA-DB22	[SUPRA]	2020-2022	418	
3BA-DB26		2022-2023	10	
3BA-DB82		2020-2022	185	
3BA-DB86		2022-2023	4	
		TOTAL	617	