

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import Vehicles~~

CAMPAIGN No.	5781	DATE	February 26, 2026
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	With regards to fuel tanks used for repairs, due to inappropriate welding of the internal partition plates, a partition plate may detach under vehicle vibration and interfere with fuel level gauge float. Thus, fuel gauge may not indicate the correct fuel level, which could lead to unexpected fuel depletion, and the engine might stall while driving.		

Vehicles which had the affected parts installed after they rolled off the assembly line.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	
LKG-GK5XAB QKG-GK5XAB QPG-GK5XAB	Quon	2011-2018	14	
QPG-GK5XAE		2015	1	
QKG-GK5XAE		2018	1	
LKG-GK6XAB QKG-GK6XAB		2010-2018	23	
QKG-GK6XAD		2013-2017	4	
		TOTAL	43	

The affected parts shipped as repair part, but the vehicles with its installed, cannot be identified.

PART NAME	PART NO.	SHIPMENT YEAR	NUMBER OF PARTS
Fuel tank	1720102Z2B	2024-2025	9
		TOTAL	9