

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5787	DATE	Mar. 5. 2026
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain vehicle control ECUs, due to an improper writing program for control values, an incorrect vehicle identification number (VIN) may be written to the engine ECU. Therefore, the VIN may not be displayed on diagnostic tools, causing the vehicle fail to comply with safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-FN1AGG	[HINO Profia]	2019~2021	44
2DG-FN1AJG		2019~2021	223
2DG-FQ1AJG		2019~2021	99
2DG-FQ1AJJ			
2DG-FR1AHA		2019~2021	1, 926
2DG-FR1AHG			
2DG-FR1AHJ			
2NG-FR1AHH			
2NG-FR1AHS			
2DG-FR1AJG		2019~2021	14
2DG-FR1EHG		2019~2021	466
2DG-FR1EHJ			
2DG-FS1AHA		2019~2021	210
2DG-FS1AHG			
2DG-FS1AHJ			
2DG-FS1EHA		2019~2021	120
2DG-FS1EHG			
2DG-FW1AHG		2019~2021	4, 943
2DG-FW1AHJ			
2NG-FW1AHH			
2NG-FW1AHS			
2DG-FW1AJG		2019~2021	25
2DG-FW1AJJ			
2DG-FW1EHG		2019~2021	671
2DG-FW1EHJ			
2DG-SH1AGGG		2020~2021	86
2DG-SH1EDGG		2020~2021	1, 189
2DG-SH1EDGJ			
2DG-SH1EEGG		2020~2021	389
2DG-SH1EGGG		2020~2021	33
	TOTAL		10, 438