

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5780	DATE	March 12, 2026
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	Due to insufficient control of detection equipment during the production process of studless tires used on large trucks and buses, inadequate rubber adhesion to the steel reinforcement material in the sidewall area may occur, resulting in reduced rubber thickness on the inner surface of the tire. Thus, the sidewall may become damaged (such as bulging or cracking) during operation, causing air leakage and, in the worst case, a risk of tire burst.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
2RG-CG5FA	Quon	2024	1
		TOTAL	1