

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5786	DATE	March. 12. 2026
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>In the engine, while the vehicle is running, engine oil may sometimes be drawn into the combustion chamber and burned due to a rough cylinder surface caused by improperly managed cylinder machining process, leading to increased oil consumption. For this reason, abnormal noise may occur due to the oil's insufficient lubrication. If the vehicle continues to be operated without corrective action, the engine may fail while running, which can cause the rear wheel to lock and potentially lead to a tip-over or fire.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-PC40	「CBR600RR」	2024~2025	2,389
TOTAL			2,389