

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5788	DATE	March.12.2026
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>In the front roof panel, due to inappropriate instructions for the process of adhering the roof panel and bracket to the body panel, there was a possibility that the area where the adhesive was applied was insufficient. As a result, water may enter this area and could cause the adhesive to peel off over time. If the vehicle is continuously operated under this condition, in the worst case, the roof panel could detach due to wind pressure while driving, which could become a road hazard for other road users.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
ZBC-MUM1NAE	[SORA]	2018-2025	196	
		TOTAL	196	