

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5791	DATE	March 26,2026
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	Due to insufficient assembly instructions for the cowl louver to the vehicle body, rain water and other fluids may leak into the brake booster through the waterproof seal. If a vehicle with this condition is used over time, rust may quickly develop. In the worst case, a hole may open in the brake booster, possibly resulting in the increase of the brake pedal effort and a longer braking distance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LA150S	MOVE	2018-2023	172,632
3BA-LA150S			
5BA-LA150S			
DBA-LA160S			38,977
3BA-LA160S			
5BA-LA160S			
DBA-LA700S	WAKE	2016-2022	108,530
3BA-LA700S			
4BA-LA700S			
DBA-LA710S			19,868
3BA-LA710S			
4BA-LA710S			
HBD-LA700V	HIJET Caddie	2016-2021	3,179
HBD-LA710V			1,067

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LA150F	STELLA	2018-2023	12,850
5BA-LA150F			
DBA-LA160F			6,322
5BA-LA160F			
DBA-LA700A	PIXIS MEGA	2016-2022	35,720
3BA-LA700A			
4BA-LA700A			
DBA-LA710A			6,818
3BA-LA710A			
4BA-LA710A			
		TOTAL	405,963