

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5796	DATE	March. 26. 2026
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>In the electric wiring system, the main harness and the power relay cord may be inappropriately secured sometimes, which causes the angle sensor coupler connected to the main harness to interfere with the locking section of the fuel hose. For this reason, if the vehicle continues to be used as is, the fuel hose may come off, resulting in fuel leakage, which may lead to a fire in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-SC86	「CB1000 HORNET」 「CB1000 HORNET SP」	2024～2025	620
		TOTAL	620