

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5802	DATE	Mar. 30 2026
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	<p>A pipe clamp for the exhaust front pipe may be installed in the wrong position due to incorrect work instruction. As a result, the bolt and nut tightening the pipe clamp may not have the required preload force. Therefore, if vehicles are used in this condition, the bolt and nut may loosen. In the worst case, the nut or bolt may fall off on the road.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FU84HZ	「FUSO SUPER GREAT」	2024 ~ 2024	3
		TOTAL	3