

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5803	DATE	Apr.8.2026
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the low-pressure fuel pump, due to the improper material of the impeller in the fuel pump, the impeller could swell and deform in the fuel. If this were to occur, the impeller may interfere with the fuel pump body and fuel pump becomes inoperative, and in the worst case, resulting in engine stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
DBA-USC10 5BA-USC10	[RC F]	2014-2022	2,755	
DBA-URL10	[GS F]	2015-2020	1,658	
TOTAL			4,413	