

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5811	DATE	April. 21. 2026
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>In the removable portable battery equipped on electric motorcycles, due to the improperly managed exterior processing of and the inappropriately set electrode layer outer diameter of the battery cell, the residual stress upon processing and the electrode layer expansion stress may cause cracks on the cell exterior, leading to electrolyte leakage. This may lower the cell voltage, causing charging problems, or the leaked electrolyte may precipitate metal, resulting in a short circuit. In the worst case, the cell may ignite, leading to a fire.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAD-EF07	「BENLY e I」	2022～2023	23,907
ZAD-EF08	「BENLY e I PRO」		
ZAD-EF09	「BENLY e I MD」		
ZAD-EF10	「BENLY e II」		
ZAD-EF11	「BENLY e II PRO」		
ZAD-EF12	「BENLY e II MD」		
ZAD-EF13	「GYRO e:」		
ZAD-EF14	「GYRO CANOPY e:」		
ZAD-EF16	「EM1 e:」		
ZAD-EF18	「CUV e:」		
		TOTAL	23,907