

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5817	DATE	7-May-26
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	In the cab of a combine harvester, the door handle mounting bolts may gradually loosen during operation due to improper tightening torque. Consequently, if the machine continues to be used in this condition, the bolts may come loose, causing the door handle to detach from its pivot point and potentially preventing the door from opening or closing from either inside or outside the cab.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
-	「YH6135」	2024～2026	189	
	「YH7135」	2024～2026	88	
TOTAL			277	