

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5815	DATE	May. 12. 2026
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	The design of the turn signal circuit in the speedometer was inappropriate. Because of this, the control system that detects circuit breakage may not function properly, potentially causing a false determination that the circuit is broken. As a result, the turn signals may fail to operate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-DM17J	TENERE700	2025	466
		TOTAL	466