

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5820	DATE	May 15, 2026
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	In the parking brake cylinder, the cylinder piston seal has been installed in the incorrect orientation due to improper assembly. If the machine continues to be operated in this condition, oil leakage may occur from the parking brake cylinder, and in the worst case, the oil pressure drop warning may be activated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDP-WA138	WA150-8	2025-2026	41
YDR-WA137	WA200-8	2025-2026	34
YDP-WR005	WR12-8	2025	1
YDR-GD035	GD405-7	2025-2026	11
TOTAL			87