

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5823	DATE	May. 28. 2026
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	During recall work, the low pressure fuel pump replacement was performed improperly, including reuse of lock nuts that should have been replaced and fastening without using specified tools after assembly. For this reason, if the vehicle continues to be used without any corrective measure, the pump may lose its sealing capability, resulting in fuel leakage from the mounting area of the pump.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-JF1	「N-BOX」、 「N-BOX Custom」	2017	6
	「N-BOX +」		1
	「N-BOX SLASH」	2017～2019	42
DBA-JF2		2018	1
DBA-JF3	「N-BOX」、 「N-BOX Custom」	2017～2019	1,177
DBA-JF4			84
6BA-JF3		2019～2020	65
6BA-JF4		2019	2
DBA-GK3	「FIT」	2017～2019	148
DBA-GK4			10
DBA-GK5			15
DAA-GP5			176
DAA-GP6			13
DBA-GB5			149
DBA-GB6	「FREED」、 「FREED+」	2018～2019	7
DAA-GB7		2017～2019	171
DAA-GB8			8
DBA-JH1	「N-WGN」	2018～2019	289
DBA-JH2	「N-WGN CUSTOM」		6
6BA-JH3	「N-WGN」	2019～2020	43
6BA-JH4	「N-WGN Custom」		5
DBA-RU1	「VEZEL」	2017～2019	60
DBA-RU2			6
DAA-RU3			129

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-RU4	「VEZEL」	2017～2019	17
HBD-JJ1	「N-VAN」	2018～2020	141
HBD-JJ2		2018～2019	62
DBA-RP1	「STEPWGN」	2017～2019	14
DBA-RP2		2019	1
DBA-RP3		2017～2019	94
DBA-RP4			3
6AA-RP5			80
DBA-GK8		「SHUTTLE」	
DBA-GK9	2018		1
DAA-GP7	2017～2019		68
DAA-GP8			5
6AA-GP7	2019		18
6AA-GP8			1
DBA-RC1	「ODYSSEY」	2017～2019	24
DBA-RC2		2018	1
DAA-RC4		2017	9
6AA-RC4		2017～2019	51
DBA-JG1	「N-ONE」		70
DBA-JG2			4
DBA-GM6	「GRACE」	2017～2018	3
DAA-GM4		2017～2019	13
DAA-GM5		2018	1
DAA-CR7	「ACCORD」	2017～2019	15
DBA-FR5	「JADE」	2018	2
DAA-FR4		2017～2019	9
DBA-JW5	「S660」		
6LA-ZC5	「CLARITY」	2018～2019	2
DAA-KC2	「LEGEND」	2018	2
DBA-FC1	「CIVIC」	2018	6
DBA-FK7		2017～2018	12
DBA-FK8		2018	3
6BA-FK7		2020	1

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
			TOTAL
			3,364