

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5826	DATE	Jun. 3. 2026
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain supply pumps used for replacement and repair, due to an inappropriate surface treatment process, the strength may be insufficient. Therefore, cracks may develop when repeatedly operated under high load, causing fuel to leak.		

Vehicles which had the affected parts installed after they rolled off the assembly line.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-FR1EXYG	[HINO Profia]	2007	1
BDG-FR1EZYJ		2007	1
BDG-FS1EKXA		2008	1
BDG-FS1EWYG		2009	1
ADG-FW1EWYA		2006	1
KS-FW1EXWG		2003、2004	2
KS-FW1EXWJ			
KS-SH1EDJG		2004	1
ADG-SH1EDXG		2006	1
ADG-SH1EGXG		2006	1
ADG-SS1EKXA		2006	1
PKG-RU1ESAA	[HINO Selega]	2010	1
		TOTAL	12