

VEHICLE SAFETY／POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5822	DATE	05 June 2026
MANUFACTURE	Hitachi Construction Machinery Co.,Ltd.		
DESCRIPTION OF DEFECT	In the control device of a shovel loader, due to an improper structure of the automatic return mechanism for the turn signal indicator, operating the mechanism at certain handle positions may cause interference between the internal pin and lever. As a result, it may obstruct the operation of the turn signal indicator or the handle, potentially preventing normal driving operation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARK
YDR-NTMA	「ZW140-7」	2025-2026	48	
YDR-NTLA	「ZW160-7」	2025-2026	18	
YDR-NTKA	「ZW180-7」	2024-2026	143	
YDS-NUDA	「ZW220-7」	2024-2026	59	
YDS-NUEA	「ZW250-7」	2025-2026	2	
		TOTAL	270	