

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5798	DATE	10, 6, 2026
MANUFACTURER	Logisnext Co., Ltd		
DESCRIPTION OF DEFECT	In the lighting systems of battery-powered forklifts, improper machining of components that make up the brake switch may cause the switch shaft to tilt, resulting in sticking during operation. Consequently, the switch may become stuck, potentially causing the brake lights to remain illuminated. Furthermore, if the forklift continues to be used in this condition, the mounting bracket may deform, potentially causing the brake lights to fail to illuminate. Additionally, during the deformation process, the force required to operate the brake pedal may temporarily increase.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ZAF-22C0	「ALESIS」	2024 – 2025	781
ZAF-24C0			389
ZAF-24D0			3
ZAF-25C0			26
		TOTAL	1,199