

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5830	DATE	June .11. 2026
MANUFACTURER	Kawasaki Motors, Ltd.		
DESCRIPTION OF DEFECT	Due to improper process control during the manufacturing of turn signal lamp bulbs, some bulbs may contain foreign material or have cracks. As a result, the filament may be damaged prematurely, which may cause the turn signal lamp to fail to illuminate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
8BK-BJ230A	「W230」 「MEGURO S1」	2025～2026	9,857	
		TOTAL	9,857	