

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5837	DATE	June. 18. 2026
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	In the front brake, due to inappropriate component management during manufacturing and improper factory repair work, some front wheel brake cable has been overadjusted with air remaining in the master cylinder. For this reason, the brake pressure remains applied unintentionally during use with the front brake drag. In the worst case scenario, the front wheel may lock up, causing the vehicle to fall.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BH-AF78	「Dunk」	2024	7
TOTAL			7