

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5831	DATE	June 29, 2026
MANUFACTURE	TOYOTA INDUSTRIES CORPORATION		
DESCRIPTION OF DEFECT	In internal-combustion forklifts equipped with LPG pressure gauge, due to inappropriate design instructions, if pressure exceeding specifications is repeatedly applied, the pressure gauge pointer may become misaligned. As a result, the actual fuel level will not match the gauge reading, and this may cause the fuel level to appear higher than actual. Therefore, if the vehicle continues to be operated, in the worst case, it may run out of fuel and become unable to travel.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7FGL18	TOYOTA GENE0	2005 - 2006	3
7FGL25		1999	2
7FG18		2006	1
407FG25		2002 - 2004	10
EBT-8FGL18		2006 - 2021	14
EBT-8FGL25		2009 - 2022	11
EBT-8FGL30		2007 - 2024	4
EBT-8FG18		2008 - 2022	21
EBT-8FG25		2007 - 2020	8
EBT-8FGJ35		2010 - 2018	3
EBT-A7FGK40		2014	1
		TOTAL	78