

VEHICLE SAFETY／POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ☒ Import Vehicles

CAMPAIGN No.	5847	DATE	01.07.2026
MANUFACTURE	Hitachi Construction Machinery Co.,Ltd.		
DESCRIPTION OF DEFECT	In the monitor panel, which serves as the instrument panel of the tire roller, some units have improperly installed waterproof packing during manufacturing. As a result, water may penetrate into the panel, and if the functionality of the LCD display is impaired, there is a risk that the odometer will not display correctly.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARK
YDN-TAEA	「ZC220P-7」	2024-2025	29	
		TOTAL	29	