

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	5850	DATE	2026/7/10
MANUFACTURER	MORITA CORPORATION 1-5, Techno Park, Sanda-shi, Hyogo, 669-1339, Japan		
DESCRIPTION OF DEFECT	In the brake lines of certain fire pump trucks, a component at the branch connection point of the auxiliary braking device (brake line lock device)—which maintains brake pressure to the front wheels while the fire pump is in operation—is missing. As a result, the connection cannot maintain a proper seal, causing brake fluid to leak. If the vehicle continues to be used in this condition, the brake warning light may illuminate, and in the worst case, braking performance may be reduced. A corrective measure will be implemented to install the “inverted flare” part. ※ No overseas production		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BF-TRY230	Toyota Dyna	2023～2026	264
TOTAL			264

(日本工業規格A列4番)