

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5851	DATE	July 15, 2026
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	In some shovel loaders, due to improper parts management, a 12V incandescent bulb may have been installed in the license plate lamp of vehicles designed for 24V operation. As a result, applying 24V to the bulb may cause abnormal overheating, which could break the filament and cause the license plate lamp to stop working.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDR-WA135	WA320-8	2026	10
YDS-WA130	WA380-8	2026	3
TOTAL			13