

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5849	DATE	July.16, 2026
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	On the battery, due to insufficient design consideration of the fastening structure of the negative terminal, moisture and the like splashed up during driving may accumulate, resulting in premature corrosion of the fastening bolt. Therefore, if the vehicle continues to be used in this condition, the fastening bolt may break, causing the starter to become inoperative and the engine to be unable to start.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BD-S500P	HIJET TRUCK	2021-2025	57,179
3BD-S510P			215,421
3BD-S500U	PIXIS TRUCK		3,400
3BD-S510U			9,979
3BD-S500J	SAMBAR TRUCK		1,741
3BD-S510J			11,028
		TOTAL	298,748