

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5829	DATE	July 17, 2026
MANUFACTURER	AICHI Corporation		
DESCRIPTION OF DEFECT	Description of Defect and Potential Risk It has been determined that the strength evaluation of the lock mechanism for the foldable tray used to store safety cones on aerial work platforms was insufficient. Due to this inadequacy, the lock mechanism may be damaged by vibrations during vehicle operation. If the lock mechanism is damaged, it may disengage while the vehicle is in motion, causing the tray to tilt. As a result, the stored safety cones may fall off the vehicle, potentially obstructing surrounding traffic and posing a safety hazard to other road users. Corrective Action All affected vehicles will be remedied by replacing the lock mechanism with an improved component that has sufficient strength and durability.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-NKS88AN	ISUZU ELF	2021-2023	22
2RG-NKR88AN	ISUZU ELF	2022	1
2RG-NKR88AM	ISUZU ELF	2024-2025	9
2RG-XZU600X	HINO DUTRO	2020-2023	105
2KG-XZU600X	HINO DUTRO	2023-2026	7
2RG-XZU605M	HINO DUTRO	2020-2023	10
2KG-XZU605M	HINO DUTRO	2023	1
2DG-XZU675M	HINO DUTRO	2024-2026	8
2KG-XZU675M	HINO DUTRO	2021-2023	35
TOTAL			198