

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/ Import Vehicles

CAMPAIGN No.	5853	DATE	Jul. 22. 2026
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain engines, the blow-by gas exhaust port is in an inappropriate location within the cylinder head cover, which would allow the oil to enter the combustion chamber through this exhaust port when excessive oil accumulates inside the head cover due to continuous driving on inclines. This can cause abnormal combustion in the combustion chamber, damaging the connecting rods and engine, and in the worst case, potentially resulting in a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-FR1AHG	[HINO Profia]	2018～2021	3
2DG-FS1AGA		2020	1
2DG-FS1AHG		2020	1
2DG-FW1AHG		2017～2018	4
		TOTAL	9