

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5857	DATE	28-Jul-26
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO.,LTD.		
DESCRIPTION OF DEFECT	In certain single-vehicle transport trailers, due to inappropriate work instructions during manufacturing, a 24 V power supply wire was mistakenly connected to the license plate lamp. As a result, the supplied voltage significantly exceeded the lamp's rated voltage, causing the filament to overheat and break. Consequently, the license plate lamp fails to illuminate, resulting in non-compliance with the applicable safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FEB80	FUSO CANTER	2025-2026	10
2PG-FEB90	FUSO CANTER	2025-2026	2
2PG-FEC90	FUSO CANTER	2025-2026	2
2PG-FED90	FUSO CANTER	2025-2026	2
2RG-FEB80	FUSO CANTER	2025-2026	23
2RG-FEB90	FUSO CANTER	2025-2026	6
2RG-FEC90	FUSO CANTER	2025	1
2RG-FED90	FUSO CANTER	2026	1
		TOTAL	47