

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5859	DATE	July 28, 2026
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	In LPG-fueled forklifts, due to improper assembly instructions for the vaporizer hose, some units have hoses that are not fully inserted and clamps secured in incorrect locations. Consequently, repeated loads—such as engine vibration—can cause cracks to form in the hose near the clamp attachment point; continued use in this condition poses a risk of LPG leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBT-M292	FG35N-10	2025	1
EBT-M293	FG35-10 FG45-10 FG50A-10	2023-2025	5
TOTAL			6