

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5856	DATE	4, 8, 2026
MANUFACTURER	Logisnext Co., Ltd		
DESCRIPTION OF DEFECT	In the axle tube of the double-tire forklift, improper quality control may result insufficient machining precision on the mating surface. As a result, repeated acceleration, deceleration, and turning may reduce the fit retention force of the tube. In the worst case, the tube may detach from the tube Assy, leading to loss of driving capability.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
YDN-F203	「FX」	2024 – 2025	48
YDN-F204			13
		TOTAL	61