

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No..	5863	DATE	August-26-2026
MANUFACTURER	PABCO CO.,LTD		
DESCRIPTION OF DEFECT	On certain vehicles, the spare tire carrier bracket installed between the frame rails at the rear overhang may have been inadequately welded to the frame. As a result, repeated vibration during vehicle operation may cause the welds to crack and separate. In the worst case, the spare tire carrier may detach, allowing the spare tire to fall from the vehicle and create a hazard for other traffic.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-FRR90S2	FORWARD	2022	7
2RG-FTR90U2		2022	4
2KG-FD2ABA	HINO RANGER	2022	1
2PG-FE2ACG		2022	1
2KG-FK62FY	FUSO FIGHTER	2022	1
		TOTAL	14