

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5873	DATE	Aug.26.2026
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	During repeated engine starts and in start-stop operation, the contacts experience abnormal wear, and wear particles may accumulate beneath the lower contact point. Over the service life of the starter, this impairs the engine's starting capability. Under certain circumstances, it may no longer be possible to start the engine. In the worst-case scenario, there is a risk of fire either when activating the starter or while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
3BA-DB26	[SUPRA]	2022-2025	507	
3BA-DB86		2023-2025	283	
		TOTAL	790	