

KOKU-KU-KI-924

No. TCD-6771-2006

Date of Issue: January, 19, 2006

Japan Civil Aviation Bureau

TAIKUSEI-KAIZEN-TSUHO

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

Applies to : Kawasaki BK117 C-2 Helicopters equipped with External Loudspeaker for Ground Personal, P/N B853K1801-051/ -053/ -055.

2. Compliance required as indicated, unless already accomplished.

To prevent loudspeaker from dropping due to crack in support bracket of the loudspeaker, accomplish the following.

- 2.1 After the effective date of this AD, check repeatedly the support bracket for cracks at every pre-flight check in accordance with Kawasaki Service Bulletin No. KSB-117-254 or later JCAB-approved revisions (SB).
- 2.2 Within 300 flight hours after the effective date of this AD, replace the support bracket with a new bracket in accordance with the SB.
- 2.3 Replacement of the support bracket of the paragraph 2.2 constitutes terminating action of the repetitive check of the paragraph 2.1 of this AD.
- 2.4 An alternative means of compliance with this AD may be used, if approved by the Director-General of JCAB.

3. Remarks

- 3.1 This AD becomes effective on February 2, 2006.
- 3.2 Kawasaki Service Bulletin No. KSB-117-254 dated November 8, 2005 and later JCAB-approved revisions pertain to this subject.

This is the English translation. In case of any difficulty, refer to the Japanese original text.