

KU-KEN- 266

No.TCD- 1188-75

Date May. 6, 1975

Japan Civil Aviation Bureau

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

1. Applies to: All Mitsubishi MU-2 Series Aircraft.

2. Compliance required as indicated

To prevent the failure of the propeller pitch control lever, unless already accomplished, immediately after the effective date of this AD, comply with the instructions of Mitsubishi MU-2 Service Bulletin No. 168 dated Apr. 18, 1975 or the later JCAB approved revisions.

3. Remarks

3.1 Effective Date: May. 23, 1975

3.2 Mitsubishi MU-2 Service Bulletin No. 168 dated Apr. 18, 1975 or the later JCAB approved revisions pertaining to this subject.